

Lott Carey Deep Well and Water Tower Project



(Left) Unused well
Below (broken pipes)



Left – Water tower’s piping disconnected
People had to use hand pumps to fill buckets with water for drinking and flushing toilets



Toilet without piping...



the school without running water, pipes were broken



Groundbreaking for new well



A new deep well is being dug. During the rainy season, the shallow wells would become contaminated. Trenches are dug for piping.





Now the water tower and the school building is set with new piping.



Water is available at the school and at a community facility on the grounds.



Children who were used to just squatting had to learn the proper use of the toilet.



The community facility is locked to control water distribution and prevent people from leaving the faucets running.

